

The Metrological and Financial Implications of a Clogged Fan-Filter!

*Martin Aust / Hewlett-Packard
Greg Burnett / Hewlett-Packard
Mike Hutchins / Hewlett-Packard*

When you've peeked around the back of an ATE system, have you ever discovered one or more dirty or clogged fan filters?

If not, then congratulations!

Maybe your work environment approaches 'clean room' quality – or maybe your preventive maintenance program is effective enough to keep the filters clean.

However, it's reasonable to consider that the majority of systems are operating in environments and processes that:


- Degrade metrological integrity; and,
- Increase equipment maintenance cost and downtime.

How serious are these effects? It may help to consider the following scenario, drawn from a number of real situations.

The Scenario

Over a period of months, the air filter for an instrument in your ATE system gradually becomes clogged. The internal operating temperature gradually rises and some metrological parameters gradually drift. At some point, due to circuit temperature coefficients, the instrument goes out of specification. Unaware of this problem, you continue to use the instrument!

Of course, the air filter continues to collect debris. Eventually – maybe weeks later – you smell something



burning. Almost simultaneously, the instrument goes into hard failure. Now for the first time, you become suspicious, to say the least. You search, inspect and ponder and it doesn't take long for you to spot the clogged air filter.


Although the cause of this dilemma is now obvious, perhaps you don't even want to think about the metrological and financial effects. The truth is that, for some unknown period of time, you have been using an out-of-tolerance instrument in your production process. *This is the metrological impact!*

Furthermore, your system is now inoperative due to the failure. This downtime translates to lost income, and almost certainly, to customer dissatisfaction. And, due to the nature of heat damage and the associated repair process, the instrument is likely to be out of service for weeks. When you have the instrument repaired and recalibrated, it will more than likely be at great expense because there are multiple failures.

Eventually, you get the instrument back and begin using it again. Unfortunately, due to the original heat-damage incident (See "Fan Filter," page 4)

HP 8711A Network Analyzer Spare Parts Kit Is Now Available

John Vallelunga / Hewlett-Packard



Hewlett-Packard has just introduced two new spare parts kits for the 8711A RF Network Analyzer. These kits will allow any user to quickly repair more than 80 percent of any failures. The intended customers are those users who have a medium-to-large installed base and require a minimal downtime.

The standard kit is HP P/N 08711-60133 for the 50 ohm 8711A. HP P/N 08711-60134 is available for 75 ohm units (Option 1EC). Both are provided at a substantial discount over the indi-

Table 1. HP 8711A Test Equipment

Equipment	Equipment Notes
438A or 437B Power Meter	436A will not work
8482A Sensor	Required for both 50 and 75 ohm units
8481D Sensor	Required for all attenuator units (Opt 1E1)
08711-60017 Service Cable	Part of 08711-60010 service kit
11852B Minimum Loss Pad	Required only for 75 ohm units (Opt 1EC)
Cal Kit (85032B/E 50 ohm)	(85036B/E for 75 ohm units)
8116A Function Generator	
8496A/G 10dB Step Atten	With Cal data
Computer: HP Series 200/300	
30dB SMA pad and short SMA cable - need not be calibrated.	

vidual assembly prices. Each kit contains the following assemblies:

- A2 CPU
- A3 Frac-N
- A4 Source
- A5 Receiver
- A6 Power Supply
- A8 Disk Drive

These assemblies will allow most all failures to be quickly repaired. Once repaired, the defective unit can be returned and a restored exchange assembly can then be purchased to restock the kit. This kit does not contain the A1

front panel, the A7 CRT, or the A8 Attenuator. These all have very low fail rates and are available separately.

In order to make the required adjustments once an assembly has been replaced, some or all of the test equipment shown in Table 1 may be required depending upon which assembly failed. This list assumes the latest 8711A firmware is used (A.02.10) as well as the latest performance test software (P/N 08711-10011). This list does not include common equipment such as cables, adapters, voltmeters, and power supplies. For complete instructions, refer to the HP 8711A Service Manual. □

Timebase Ground-Loops

Greg Burnett / Hewlett-Packard

Break the ground loop with a timebase isolation transformer!

The practice of locking the timebase of an instrument to a "house frequency standard" is a good way to improve the frequency accuracy and traceability of your measurements. However, an undesired side-effect may be a ground-loop induced measurement error for certain measurands — especially for low-level audio measurements. (In such instances, the external timebase connection may complete an unwanted ground-loop path.)

The Problem

For example, consider the following scenario: I was using an HP 3325B Synthesized Generator and an HP 3585B Spectrum Analyzer to measure the au-

dio gain of a device-under-test (DUT). I locked the 3325B and 3585B timebases to the "house frequency standard" via a distribution amplifier. I then connected a very low-level audio signal from the 3325B to the DUT's input port. The DUT amplifies the small signal (80 dB gain), which I attempted to measure by connecting the DUT's output port to the 3585B 1M ohm input port. However, I discovered the DUT was self-oscillating (which it isn't supposed to do). When I disconnected the 3325B external timebase connection, I broke the ground-loop and the problem "went away."

Many times external timebase ground-loop effects are more subtle than the above scenario. This can be even worse because moderate measurement errors may go undetected for some time. Therefore, to be safe, you may wish to

isolate most (or all) of your external timebase connections. (The problem tends to be worse when an instrument's external timebase input and main signal output are both "floating" relative to the chassis, but not relative to each other; however, many ground-loop scenarios are possible.)

The Solution

Break the timebase ground-loop by inserting isolation transformers between the frequency distribution amplifier and the external timebase input of each instrument. (Place each isolation transformer as near the external timebase input as possible.)

The isolation transformer should preferably:

1. Have 1:1 ohms ratio, with bandwidth to at least 20 MHz.




Figure 1. Block diagram showing simplified ground-loop problem

2. Be mounted in a small, shielded case with BNC connectors.
3. Break the ground-loop, but not alter the timebase signal.

The transformer may be "home-built" from suitable parts. However, as of this writing, I have used a low-cost, commercially available isolation transformer to successfully break timebase ground-loops. It is:

Mini-Circuits, P/N FTB-1-1-75 *C15
\$36.95 (U.S. Dollars)

Contact:
Mini-Circuits
P.O. Box 350166
Brooklyn, NY 11235-0003
Phone: 718-934-4500
FAX: 718-332-4661



READERS' CORNER

Dear Editor

Nice article on "Calibration of Time Base Oscillators," however, I believe there is a mistake in the Example 2 paragraph where it references Figure 3b, the Recalibration Chart for Rubidium Standards. If the chart is correct, then the recalibration time should be approximately 80 days and not 101 as the text states.

Also a note on frequency standards. The HP 5065A Rubidium Frequency Standard has been our "house frequency standard" at our manufacturing division for the last 20 years. A three month calibration cycle was established many years ago and I only have to "steer" it back to nominal approximately once a year. We still use WWVB as a calibration source due to its geographical closeness to our site. I do a 48 hour drift test for maximum accuracy.

A follow-up article on calibration sources for high-end frequency standards would be nice to see in the next *Bench Briefs*.

John Chapman/Measurement Standards & Services
Hewlett-Packard Colorado Springs

John - Thanks for catching a typographical error in our Application Note 52-2 Ap-

pendix C that has been there unknown for at least 20 years. Starting on page 2-4, a sample problem is worked out that happens to be the same example used in the appendix. At the end of the formulae on page 2-6 the correct answer of 75 days is given. However, somehow this was transposed to 101 days in the example in Appendix C, which was passed on in the *Bench Briefs* article.

As for a new frequency standard, John, look at Hewlett-Packard's new HP 58503 GPS Receiver, which will be describe in a later issue of *Bench Briefs*. For more information contact your local HP sales office.

Another reader wrote in that he preferred to see the Allowable Offset column in Table 1 to be shown in unitless fractional form to avoid confusion. Therefore, Table 1 would read as follows:

Editor



Table 1. Typical specifications of the five types of oscillators.

Time Base Type	Typical Aging	Typical Shift for 5 C°	Allowable Offset @ 10 MHz	Typical Warmup	Allan Variance (T=1 sec.)
XO	3 x 10 ⁻⁷ per month	5 x 10 ⁻⁶	60 Hz (6 x 10 ⁻⁶)	30 minutes	1 x 10 ⁻⁹
TCXO	1 x 10 ⁻⁷ per month	1 x 10 ⁻⁶	13 Hz (1.3 x 10 ⁻⁶)	3 hours	1 x 10 ⁻¹⁰
OvenXO	5 x 10 ⁻¹⁰ per day	5 x 10 ⁻¹⁰	150 mHz (1.5 x 10 ⁻⁷)	3 days	5 x 10 ⁻¹²
Rubidium	1 x 10 ⁻¹¹ per month	5 x 10 ⁻¹²	400 μHz (4 x 10 ⁻¹¹)	4 hours	7 x 10 ⁻¹²
Cesium	None (Primary Std.)	3 x 10 ⁻¹²	50 μHz (5 x 10 ⁻¹²)	45 minutes (21.5 nsec/hour)	1 x 10 ⁻¹¹

("Fan Filter," continued from page 1)

dent, many parts (that were not replaced) are functional – *but wounded*. During the following months and years, you notice the instrument has poorer reliability than before and it is not as stable between calibrations.

You might need to reduce the instrument's calibration interval according to your company's periodicity management process – a pity since the instrument previously had an extended interval based on its excellent historical performance. So, to meet metrological reliability targets, the instrument is

calibrated more often.

The *cost of ownership* – and the *inconvenience* of downtime – are disappointing, compared to what could have been.

It is without doubt that variations of this scenario do occur in normal work-environments.

The Solution

The solution to this problem is very simple

- To help preserve metrological traceability of your processes,
- To improve *your* customer's satisfaction, and
- To reduce operating costs,

all you need to do is follow a simple preventive maintenance program to inspect and clean the air filters at regular intervals.

For further information on this or advice on any other Test & Measurement Support matter, call your local Hewlett-Packard Customer Support Center. □

Safety-Related Service Notes

Service Notes from Hewlett-Packard relating to personal safety and possible equipment damage are of vital importance to our customers. To make you more aware of these important notes, they are printed on paper with a red border, and the service note number has an "-S" suffix. In order to make you immediately aware of any potential safety problems, we are highlighting safety-related service notes here with a brief description of each problem. Also, in order to draw your attention to safety-related service notes in the service note index, each safety-related service note is highlighted with a contrasting color.

HP E1550A C-Size DS1 32-Channel Daisy Chain/Multiplexer Switch

Serial Numbers Affected
3315A00100/3315A00141

The maximum input voltage for the E1550A is 42 Vpk. Some units were shipped with sheet metal (top covers) marked with an input voltage of 200 Vdc/170 Vrms. The manual does indicate the correct specification. Electric shock and/or equipment damage is possible if input voltage greater than 42 Vpk is applied.

Order Safety Service Note E1550A-01-S (document ID number 5758 on the HP FIRST system) for more information.

E3951A IPATS Primary Access Test System; Front end adapter

Serial Numbers Affected
0000U00000/9999U99999

Note: This Safety Service Note is for *information only*. All systems have been repaired and no further action is necessary.

For more information, order Priority Safety Service Note E3951A-01-S (document ID number 6166 on the HP FIRST system).

E1421A C-Size Portable Mainframe

Serial Numbers Affected
US34000101/US34000216

A potential electrical shock hazard and/or fire hazard could result if certain fault conditions were to occur in the instrument.

A possible assembly error connects the AC neutral wire in series with the fuse instead of the line wire. This error occurs on the power entry module.

Note: This wiring error only creates a problem in North America (US and Canada) and other countries that use polarized mains. For countries that do not have polarized mains and that rely on the branch circuit over-current devices for protection, the reverse wiring is not a particular issue.

For more information, order Safety Service Note E1421A-01-S (document ID number 6251 on the HP FIRST system).

J2522A & J2523A Internet LAN Advisor

Serial Numbers Affected
J2522A - 3440A00116/3440A00158
J2523A - 3439A00165/3440A00238

Due to a redesign of the chassis to meet RFI standards, there exist components that do not have the appropriate clearance to a ground point. If the power cord ground is defeated and the component arcs to ground, a shock hazard may occur.

Return your instrument to the nearest HP Service Center and it will be repaired at no charge. For more information, order Priority Safety Service Notes J2522A-01-S or J2523A-01-S as document ID numbers 6262 or 6264 from the HP FIRST system. □

1995 Bench Briefs' Instrument Service Note Index

HP FIRST (208)344-4809
 T & M Instrument Section - Press 4
 T & M Service Notes - Press 2
 Enter the Password - 76683

SN Type	SN No.	Abstract	HP FIRST Document ID No.
MR	10887B-01	New IC sockets prevent FPGAs from falling out	6125
MR	10887P-01	New IC sockets prevent FPGAs from falling out	6126
IO	11848A-03	Clarification of test failures due to pc board modification	6129
IO	16008B-01A	New thread sealant for top cover micro-switch so that adjustment is maintained	6096
MR	16008B-02	Recommended replacement of main electrode if conductive elastomer sheet is loose	6060
IO	16047C-01	Instructions on replacing the BNC connector and electrode	6061
IO	16117B-01	Rec replacement parts for black cover/gold contact plug	6148
IO	16117B-02	Design of interlock cable has been changed	6168
MR	16441A-01	Mod corrects abnormal measurement results using R-Box & Kelvin-Triaxial cables	6095
IO	16555A-01	Change in calibration procedures for multicard modules	6059
MR	1660A-01	Instructions on reloading S/W to correct Flash ROM failure	6131
MR	1660AS-01	Instructions on reloading S/W to correct Flash ROM failure	6132
MR	1661A-01	Instructions on reloading S/W to correct Flash ROM failure	6133
MR	1661AS-01	Instructions on reloading S/W to correct Flash ROM failure	6134
MR	1662A-01	Instructions on reloading S/W to correct Flash ROM failure	6135
MR	1662AS-01	Instructions on reloading S/W to correct Flash ROM failure	6136
MR	1663A-01	Instructions on reloading S/W to correct Flash ROM failure	6137
MR	1663AS-01	Instructions on reloading S/W to correct Flash ROM failure	6138
IO	3048A-02	Clarification of test failures due to pc board modification	6127
IO	3048MS-02	Clarification of test failures due to pc board modification	6128
MR	33120A-01	Higher value of output fuse makes it less likely to open	6169
MR	34401A-05A	Excessive time drift of ohms function calibration	6163
MR	3560A-02	Power off failure discharges battery	6170
MA	3562A-05C	New firmware improves performance	5273
MR	35660A-05A	New power switch improves reliability	5882
MR	35665A-01A	New power switch improves reliability	5883
MA	35670A-03	Firmware upgrade provides new features and fixes defects	6150
MR	3569A-01A	HP 3569A firmware revision history	5878
MR	3569A-03	Power off failure discharges battery	6171
IO	3577A-18	Magnitude dynamic accuracy spec changed at frequencies below 100 kHz	6065
MR	3577B-08	Modification to A18 improves source distortion at 1.0 kHz	6066
IO	3577B-09	Magnitude dynamic accuracy spec changed at frequencies below 100 kHz	6067
MR	3588A-06A	New power switch improves reliability	5880
MR	3589A-02A	New power switch improves reliability	5881
IO	37161A-01	Recommended IC replacement	6100
IO	37161C-01	Recommended IC replacement	6101
IO	37161D-01	Recommended IC replacement	6102
MR	37701A-07	Incorrect TERM level measurement on A1 Measurement Assembly	6103
MR	37701B-01	Required F/W upgrade corrects error in FULL-T1 mode and Fractional-T1 mode	6104
MR	37702A-01	Incorrect TERM level measurement on A1 Measurement Assembly	6105
MR	37702A-02	Required F/W upgrade corrects error in FULL-T1 mode and Fractional-T1 mode	6106
MR	37711A-07	Incorrect TERM level measurement on A1 Measurement Assembly	6107
MR	37724A-02	Path overhead byte programming problem fix	6108
MR	37724A-03	Modification corrects 155 Mb/x clock wander	6109
IO	3779C-46	Front panel connector panel replacement	6097
IO	3779D-50	Front panel connector panel replacement	6098
IO	3787B-13	Preferred replacement for A5 Motherboard assembly	6165
MA	3789B-04B	Modification eliminates noise from HP 3789B input port	6099
MR	4142B-12	HCU's current compliance may occur unexpectedly	6172
MR	41501A-01	New power supply prevents shut-down failures	6115
MR	4155A-02	New power supply prevents shut-down failures	6113
MR	4155A-03	Motherboard replment for SMU selftest/selfcalib error 10x24	6139
MR	4155A-04	New front panel prevents rotary knob from rubbing front panel	6140
MR	4155A-05	New front panel prevents push button keys from sticking	6141
MR	4155A-06	Replacing CPU board ROMs fixes firmware defects	6173
MR	4156A-02	New power supply prevents shut-down failures	6114
MR	4156A-03	Repair for SMU selftest/selfcalibration error 10x24	6142
MR	4156A-04	New front panel prevents rotary knob from rubbing front panel	6143
MR	4156A-05	New front panel prevents push button keys from sticking	6144
MR	4156A-06	Incorrect power-on test error codes	6174
MR	4156A-07	Replacing CPU board ROMs fixes firmware defects	6175
MR	41800A-03	Recommended replacement nose assembly for probe pin	6149

SN Type	SN No.	Abstract	HP FIRST Document ID No.
MR	4194A-14	Hang-up at power-on in the low temperature	6176
MR	4195A-18	Hang-up at power-on in the low temperature	6177
IO	4276A-06A	Repair method for the A1 logic board	6178
MR	4276A-08	Repair information for resistance accuracy test failures	6179
MR	42841A-04B	Mod prevents bias current source fuses from blowing	5405
MR	4284A-11A	Modification prevents bias current source fuse from blowing	5402
MR	4285A-09A	Mod prevents bias current source fuse from blowing	5403
MR	4291A-02	New firmware corrects some bugs in F/W revision 3.00 and 3.01	6145
MR	4291A-03	New firmware corrects some bugs on firmware revision 3.00 through 3.02	6180
IO	4396A-01C	Firmware Update and A1 CPU repair information	5642
MR	4396A-13	New firmware corrects some bugs in firmware revision 3.00	6146
MR	4396A-14A	New firmware corrects incorrect HP-IB return value of "*TST?" query	6147
IO	4985A-01	Procedure to dnlod main sys brd MAC addr when replacing board	6158
MR	4995A-02	Jumper wires in serial controller chip improve performance	6122
IO	4995A-03	Procedure to dnlod main sys brd MAC addr when replacing board	6159
MR	4996A-02	Jumper wires in serial controller chip improve performance	6123
IO	4996A-03	Procedure to dnlod main sys brd MAC addr when replacing board	6160
IO	5334A-07	A1U22 input Schmitt amplifier part change	6181
IO	5334B-08	A1U22 input Schmitt amplifier part change	6182
MA	5335A-17C	Replacement of the 5335A Front End Schmitt Amplifiers	5597
IO	5372A-07	Performance test procedure for using 1 meg pods	6164
MR	66000A-03	A1-U1 may short due to overshoots in the bias supply	6183
MR	66000A-04	New F/W prevents unit from briefly re-asserting SRQ after a serial poll	6184
MR	66101A-02	Power supply may OV when load is removed at high output voltages	6185
MR	66105A-02	Supply may oscillate below .15 volts	6186
IO	6621A-07	If newly designed ac input module is replaced, associated cables need replacing	6072
IO	6621A-08	If newly designed pwr modules U338/339 are replaced, heatsink must be isolated	6073
IO	6622A-05	If newly designed ac input module is replaced, associated cables need replacing	6074
IO	6622A-06	If newly designed pwr modules U338/339 are replaced, heatsink must be isolated	6075
IO	6623A-09	If newly designed ac input module is replaced, associated cables need replacing	6076
IO	6623A-10	If newly designed pwr modules U338/339 are replaced, heatsink must be isolated	6077
IO	6624A-07	If newly designed ac input module is replaced, associated cables need replacing	6078
IO	6624A-08	If newly designed pwr modules U338/339 are replaced, heatsink must be isolated	6079
IO	6625A-03	If newly designed ac input module is replaced, associated cables need replacing	6080
IO	6625A-04	Replacement power module must be isolated from ground	6187
MR	6625A-05	Replacement of failed diode corrects out of spec programming accuracy	6188
IO	6626A-03	If newly designed ac input module is replaced, associated cables need replacing	6081
IO	6626A-04	Replacement power module must be isolated from ground	6189
MR	6626A-05	Replacement of failed diode corrects out of spec programming accuracy	6190
IO	6627A-01	If newly designed ac input module is replaced, associated cables need replacing	6082
IO	6627A-02	If newly designed pwr modules U338/339 are replaced, heatsink must be isolated	6083
IO	6628A-03	If newly designed ac input module is replaced, associated cables need replacing	6084
IO	6628A-04	Replacement power module must be isolated from ground	6191
MR	6628A-05	Replacement of failed diode corrects out of spec programming accuracy	6192
IO	6629A-03	If newly designed ac input module is replaced, associated cables need replacing	6085
IO	6629A-04	Replacement power module must be isolated from ground	6193
MR	6629A-05	Replacement of failed diode corrects out of spec programming accuracy	6194
MR	6671A-02	Mod prevents Error -240 from occur when cond to HP 59510A/11A Relay Box	6086
MR	6672A-02	Mod prevents Error -240 from occur when conn to HP 59510A/11A Relay Box	6087
MR	6673A-02	Mod prevents Error -240 from occur when conn to HP 59510A/11A Relay Box	6088
MR	6674A-02	Mod prevents Error -240 from occur when conn to HP 59510A/11A Relay Box	6089
MR	6675A-03	Mod prevents Error -240 from occur when conn to HP 59510A/11A Relay Box	6090
MR	6812A-01	Mod prevents intermittent voltage or current readback error	6195
MR	6812A-02	Mod corrects unbalanced voltage distribution in 15V bias circuits	6196
MR	6812A-03	Mod corrects unequal voltage distribution on output board	6197
MR	6812A-04	Mod prevents excess ripple current in output capacitors	6198
MR	6813A-01	Mod prevents intermittent voltage or current readback error	6199
MR	6813A-02	Mod corrects unbalanced voltage distribution in 15V bias circuits	6200
MR	6813A-03	Mod corrects unequal voltage distribution on output board	6201
MR	6813A-04	Mod prevents excess ripple current in output capacitors	6202
MR	6814A-01	Mod corrects intermittent voltage or current readback error	6203
MR	6834A-01	New ROMs prevent power-on failure when in RS-232 interface mode	6121
MR	6834A-02	Mod corrects intermittent voltage or current readback error	6204
IO	70820A-03	Fractional N and local oscillator board repair strategy	6205
IO	70900A-14L	List of firmware compatibility and history	5618
IO	70900B-01G	List of firmware compatibility and history	5619
MR	81000FI-01	Loose retaining ring may cause higher insertion loss	6206
MR	81000FI-02	Cracked ceramic bushing may result in high insertion loss	6207
IO	81533A/B-01	New power sensor module extends power range to +30 dBm	6058
IO	83630A-01	Recalibration of service software improves calibration	6208

SN Type	SN No.	Abstract	HP FIRST Document ID No.
IO	83650A-01	Recalibration of service software improves calibration	6209
IO	8483A-04	Shims may be needed to stabilize the RF center conductor	6210
MR	85420E-01	EEROM Firmware Upgrade	6211
MR	85422E-01	EEROM Firmware Upgrade	6212
MR	85460A-01	EEROM Firmware Upgrade	6213
MR	85462A-01	EEROM Firmware UpgradE	6214
MA	8560E-04D	Firmware upgrade kit improves performance	5797
MA	8561E-03D	Firmware upgrade kit improves performance	5798
MA	85620A-02A	Firmware upgrade kit improves performance	6120
MA	8563E-04D	Firmware upgrade kit improves performance	5799
MR	8563E-10	Replacement A10 corrects frequency response	6215
MA	8564E-01C	Firmware upgrade kit improves performance	6004
MR	8564E-03	Modification prevents 5v power supply from limiting at turn-on	6152
MR	8564E-04	Replacement A10 corrects frequency response	6216
MA	8565E-01C	Firmware upgrade kit improves performance	6005
MR	8565E-03	Modification prevents 5v power supply from limiting at turn-on	6153
MR	8565E-04	Replacement A10 corrects frequency response	6217
IO	8566A-43	Recommended replacement for A10A6U2 OP AMP	6154
IO	8566B-41	Recommended replacement for A10A6U2 OP AMP	6155
IO	8590D-01	Increasing flatness data values improves performance	6218
IO	8590D-05	Defective EEPROM's can cause blank or partially blank display	6219
IO	8590D-06	How to input ID codes to identify proper analyzer	6220
IO	8590L-01	Defective EEPROM's can cause blank or partially blank display	6221
IO	8590L-02	How to input ID codes to identify proper analyzer	6222
IO	8591C-02	Defective EEPROM's can cause blank or partially blank display	6223
IO	8591C-03	How to input ID codes to identify proper analyzer	6224
IO	8591E-01	Increasing flatness data values improves performance	6225
IO	8591E-05	Defective EEPROM's can cause blank or partially blank display	6226
IO	8591E-06	How to input ID codes to identify proper analyzer	6227
IO	8592D-03	Defective EEPROM's can cause blank or partially blank display	6228
IO	8592D-04	How to input ID codes to identify proper analyzer	6229
IO	8592L-01	Defective EEPROM's can cause blank or partially blank display	6230
IO	8592L-02	How to input ID codes to identify proper analyzer	6231
IO	8593E-06	Defective EEPROM's can cause blank or partially blank display	6232
IO	8593E-07	How to input ID codes to identify proper analyzer	6233
MR	8593E-08	Mod prevents link analyzer self verification test failure	6234
IO	8594E-06	Defective EEPROM's can cause blank or partially blank display	6235
IO	8594E-07	How to input ID codes to identify proper analyzer	6236
MR	8594E-08	Mod prevents link analyzer self verification test failure	6237
IO	8595E-06	Defective EEPROM's can cause blank or partially blank display	6238
IO	8595E-07	How to input ID codes to identify proper analyzer	6239
MR	8595E-08	Mod prevents link analyzer self verification test failure	6240
IO	8596E-06	Defective EEPROM's can cause blank or partially blank display	6241
IO	8596E-07	How to input ID codes to identify proper analyzer	6242
MR	8596E-08	Mod prevents link analyzer self verification test failure	6243
IO	8711A-05	Change in adjustment procedure for units with firmware Rev A.02.10	6119
MR	87510A-09	Mod to increase moisture and dust resistance of power supply circuit	6062
MR	87510A-10	Mod prevents unit from hanging up or generating an unexpected reset	6063
MR	87510A-11	Mod prevents CRT failure that causes loss of picture on the display	6064
MR	87510A-12	Modification to fix the power-on test failure in internal test No.18	6244
MR	8751A-22A	Mod prevents unit from hanging up or generating an unexpected reset	5737
MR	8752A-02	Replacing capacitor eliminates blowing of fuse A8F10	6156
MR	8753C-04	Replacing capacitor eliminates blowing of fuse A8F10	6157
MR	8900C-10	New pc board in 08900-60218 assembly improves reliability	6124
MR	8920A-11	Firmware replacement corrects various defects	6245
MR	8920B-01	Firmware replacement corrects various defects	6246
MR	8921A-04	Firmware replacement corrects various defects	6247
MR	8922A-01	Removal of unneeded hardware prevents internal shorts	6091
MR	8922B-01	Removal of unneeded hardware prevents internal shorts	6092
MR	8922E-01	Removal of unneeded hardware prevents internal shorts	6093
MR	8922G-01	Removal of unneeded hardware prevents internal shorts	6094
MR	89410A-01E	New FW fixes problems and improves performance (includes history)	5710
MR	89410A-06	Installation of missing rope gaskets reduces radiated RF emissions	6068
IO	89410A-07	Source harmonic and other spurious products specification change	6069
MA	89430A-03	Incorrect SMA cable wrench may damage source modules	6248
MA	89431A-01A	Firmware revision history	6151
IO	89440A-06A	89410A/89430A repair strategy	6049
IO	89440A-07	Source harmonic and other spurious products specification change	6070
IO	89441A-01A	89410A/89431A repair strategy	6050
MR	E1401A-05	Pwr supply reliability improvement when operated from 230VAC	6249

SN Type	SN No.	Abstract	HP FIRST Document ID No.
MR	E1401T-01	Pwr supply reliability improvement when operated from 230VAC	6250
SA	E1421A-01-S	Miswired AC line/fuse may cause shock hazard	6251
IO	E1431A-01	High temperature failure may not be reported by diagnostics	6118
MR	E1472A-01	Mod prevents erratic operation at elevated temperatures	6110
MR	E1474A-01	Mod prevents erratic operation at elevated temperatures	6111
SA	E1550A-01-S	Possible shock hazard due to mismarked input voltage rating	6130
MR	E1662A-01	Mod prevents breakage of 81000FI Optical Connector on front panel	6252
MR	E1674A-01	New resistor improves TTL specs of trigger output when loaded at 50 ohms	6112
MR	E1696A-01	Mod prevents breakage of 81000FI Optical Connector on front panel	6253
MR	E1697A-01	Mod prevents breakage of 81000FI Optical Connector on front panel	6254
MA	E2550A-02A	New firmware improves performance	5984
MA	E2555A-01	Potential problems with record or errors on power-up	6167
MR	E3610A-03	New voltage control eliminates sporadic output voltage overshoot	6116
MR	E3611A-04	New voltage control eliminates sporadic output voltage overshoot	6117
MR	E3630A-01	Reliability improvement for supplies that fail in the field	6255
PS	E3951A-01-S	For Info Only. Repair procedure/policy elims shock hazard	6166
MR	J2301A-01	New assy allows full speed oper when used w/high spd adapters	6161
MR	J2301A-02	Modification prevents Trap Machine failures	6256
MR	J2301A-03	Modification prevents damage to power supply during power on	6257
MR	J2302A-01	New assy allows full speed oper when used w/high spd adapters	6162
MR	J2302A-02	Modification prevents Trap Machine failures	6258
MR	J2302A-03	Modification prevents damage to power supply during power on	6259
MA	J2306A-01	Optional modification upgrades the capture buffer to 16 MB	6260
MA	J2309A-01	Optional modification upgrades the capture buffer to 16 MB	6261
PS	J2522A-01-S	Possible shock hazard if earth ground of the power cord is defeated	6262
MR	J2522A-02	Modification prevents damage to power supply during power on	6263
PS	J2523A-01-S	Possible shock hazard if earth ground of the power cord is defeated	6264
MR	J2523A-02	Modification prevents damage to power supply during power on	6265

Service Note Types

IO	Information Only	SA	Safety
MA	Modification Available	PS	Priority Safety
MR	Modification Recommended		

HEWLETT-PACKARD COMPANY

100 Mayfield Avenue
Mountain View, California 94043

BENCH BRIEFS
1st Quarter 1995

Volume 35 No. 1

Service information from
Hewlett-Packard Company

To obtain a qualification form for a free
subscription, send your request to the
above address.

Reader comments or technical article
contributions are welcomed.
Please send them to the
Bench Briefs Editor at the above address.

Editor: Jim Bechtold
Hewlett-Packard

Bulk Rate
U.S. Postage
PAID
Santa Clara, CA
Permit No.
90

All rights reserved. Permission to reprint Bench Briefs granted upon written request to the Editor.

Printed in U.S.A.