

Errata
MSP430F2131 Microcontroller



ABSTRACT

This document describes the known exceptions to the functional specifications (advisories).

Table of Contents

1 Functional Advisories	2
2 Preprogrammed Software Advisories	2
3 Debug Only Advisories	2
4 Fixed by Compiler Advisories	3
5 Nomenclature, Package Symbolization, and Revision Identification	4
5.1 Device Nomenclature.....	4
5.2 Package Markings.....	4
5.3 Memory-Mapped Hardware Revision (TLV Structure).....	5
6 Advisory Descriptions	6
7 Revision History	20

1 Functional Advisories

Advisories that affect the device's operation, function, or parametrics.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev L	Rev K	Rev J	Rev I	Rev H	Rev G	Rev E	Rev D	Rev C
BCL6								✓	✓
BCL8								✓	✓
BCL9						✓	✓	✓	✓
BCL10						✓	✓	✓	✓
BCL11						✓	✓	✓	✓
BCL12	✓	✓	✓	✓	✓	✓	✓	✓	✓
BCL13					✓	✓	✓	✓	✓
BCL14	✓	✓	✓	✓	✓				
CPU5									✓
CPU11	✓	✓	✓	✓	✓	✓	✓	✓	✓
CPU14						✓	✓		
CPU45	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH16	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH17	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH18	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH19	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH20	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH22						✓	✓	✓	✓
FLASH24	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH27	✓	✓	✓	✓	✓	✓	✓	✓	✓
FLASH36	✓	✓	✓	✓	✓	✓	✓	✓	✓
PORT8								✓	✓
PORT10						✓	✓	✓	✓
SYS15	✓	✓	✓	✓	✓	✓	✓	✓	✓
TA12	✓	✓	✓	✓	✓	✓	✓	✓	✓
TA16	✓	✓	✓	✓	✓	✓	✓	✓	✓
TA21	✓	✓	✓	✓	✓	✓	✓	✓	✓
TAB22	✓	✓	✓	✓	✓	✓	✓	✓	✓
XOSC5	✓	✓	✓	✓	✓	✓	✓	✓	✓
XOSC8			✓	✓	✓	✓	✓	✓	✓

2 Preprogrammed Software Advisories

Advisories that affect factory-programmed software.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev L	Rev K	Rev J	Rev I	Rev H	Rev G	Rev E	Rev D	Rev C
BSL5									✓

3 Debug Only Advisories

Advisories that affect only debug operation.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev L	Rev K	Rev J	Rev I	Rev H	Rev G	Rev E	Rev D	Rev C
EEM20	✓	✓	✓	✓	✓	✓	✓	✓	✓
JTAG15							✓	✓	✓

4 Fixed by Compiler Advisories

Advisories that are resolved by compiler workaround. Refer to each advisory for the IDE and compiler versions with a workaround.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev L	Rev K	Rev J	Rev I	Rev H	Rev G	Rev E	Rev D	Rev C
CPU4	✓	✓	✓	✓	✓	✓	✓	✓	✓
CPU6								✓	✓
CPU12	✓	✓	✓	✓	✓	✓	✓	✓	✓
CPU13	✓	✓	✓	✓	✓	✓	✓	✓	✓
CPU19	✓	✓	✓	✓	✓	✓	✓	✓	✓

Refer to the following MSP430 compiler documentation for more details about the CPU bugs workarounds.

TI MSP430 Compiler Tools (Code Composer Studio IDE)

- [MSP430 Optimizing C/C++ Compiler](#): Check the --silicon_errata option
- [MSP430 Assembly Language Tools](#)

MSP430 GNU Compiler (MSP430-GCC)

- [MSP430 GCC Options](#): Check -msilicon-errata= and -msilicon-errata-warn= options
- [MSP430 GCC User's Guide](#)

IAR Embedded Workbench

- [IAR workarounds for msp430 hardware issues](#)

5 Nomenclature, Package Symbolization, and Revision Identification

The revision of the device can be identified by the revision letter on the [Package Markings](#) or by the [HW_ID](#) located inside the TLV structure of the device.

5.1 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all MSP MCU devices. Each MSP MCU commercial family member has one of two prefixes: MSP or XMS. These prefixes represent evolutionary stages of product development from engineering prototypes (XMS) through fully qualified production devices (MSP).

XMS – Experimental device that is not necessarily representative of the final device's electrical specifications

MSP – Fully qualified production device

Support tool naming prefixes:

X: Development-support product that has not yet completed Texas Instruments internal qualification testing.

null: Fully-qualified development-support product.

XMS devices and X development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

MSP devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (XMS) have a greater failure rate than the standard production devices. TI recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the temperature range, package type, and distribution format.

5.2 Package Markings

DGV20

TVSOP (DGV), 20 Pin




= Die revision
○ = Pin 1 location
N = Lot trace code



= Die revision
○ = Pin 1 location
N = Lot trace code


PW20

TSSOP (PW), 20 Pin




DW20

SOP (DW), 20 Pin



RGE24

QFN (RGE), 24 Pin



5.3 Memory-Mapped Hardware Revision (TLV Structure)

This device does not support reading the hardware revision from memory.

Further guidance on how to locate the TLV structure and read out the HW_ID can be found in the device User's Guide.

6 Advisory Descriptions

BCL6 *BCL Module*

Category Functional

Function DCO calibration error

Description The DCO calibration values stored in the information memory may differ by up to +- 2%. This applies to all Rev. C and the following Lot-Trace code Rev. D devices:

Lot#57FNFCK
 Lot#58E081K
 Lot#58E521K
 Lot#58F5K9K
 Lot#58F5KTK
 Lot#58F860K
 Lot#58F866K
 Lot#58FKL3K
 Lot#59C279K

Workaround Recalibrate the DCO using a reference clock source

BCL8 *BCL Module*

Category Functional

Function Erroneous ISR DCO DC generator enable

Description When MCLK and SMCLK are sourced from a clock other than the DCO, the SCG0 DCO control bit is erroneously cleared upon interrupt service routine entry from LPMx by the CPU. This enables the DCO DC generator causing additional current consumption. After executing the RETI instruction, the status register SCG0 bit will return to a set state turning off the DC generator, eliminating this added current. The increased current will only occur during the interrupt service routine, and is in the range of 20 uA at 3V.

Workaround Set SCG0 in software at the beginning of an interrupt service routine. This will reduce the time that the DC generator is enabled to four MCLK.

BCL9 *BCL Module*

Category Functional

Function ACLK divider modifications require delay before entering LPM3

Description After modifying the DIVAx bits, immediately entering LPM3 can cause the modification to be ignored and the divider settings not to take effect. Reading back the DIVAx bits will indicate the intended setting even when the divider has not been correctly applied.

Workaround When the DIVAx bits are modified, a delay of one complete ACLK (VLO or LFXT1CLK) period must elapse before entering LPM3. The delay is only necessary the first time LPM3 is entered after the DIVAx bits are modified. After the one-period delay, LPM3 may be entered and exited normally without additional delays.

BCL10 *BCL Module*

Category Functional

Function MCLK = ACLK and P2SEL control bits

Description When using ACLK as the CPU MCLK clock source, the oscillator failsafe feature does not automatically switch MCLK to the DCO if the P2SEL6 or P2SEL7 bit is cleared. This applies when ACLK = LFXT1 (external low frequency clock source). The CPU will halt operation since no MCLK signal is present.

Workaround None

BCL11 ***BCL Module***

Category Functional

Function Watchdog failsafe when using ACLK

Description When using ACLK as the WDT+ clock source, the WDT+ oscillator failsafe feature does not automatically switch to the DCO if the P2SEL6 or P2SEL7 bit is cleared. This applies when ACLK = LFXT1 (external low frequency clock source). The WDT+ will halt operation since no clock signal is present.

Workaround None

BCL12 ***BCL Module***

Category Functional

Function Switching RSELx or modifying DCOCTL can cause DCO dead time or a complete DCO stop

Description After switching RSELx bits (located in register BCSTL1) from a value of >13 to a value of <12 OR from a value of <12 to a value of >13, the resulting clock delivered by the DCO can stop before the new clock frequency is applied. This dead time is approximately 20 us. In some instances, the DCO may completely stop, requiring a power cycle.

Furthermore, if all of the RSELx bits in the BCSTL1 register are set, modifying the DCOCTL register to change the DCOx or the MODx bits could also result in DCO dead time or DCO hang up.

Workaround - When switching RSEL from >13 to <12, use an intermediate frequency step. The intermediate RSEL value should be 13.

Current RSEL	Target RSEL	Recommended Transition Sequence
15	14	Switch directly to target RSEL
14 or 15	13	Switch directly to target RSEL
14 or 15	0 to 12	Switch to 13 first, and then to target RSEL (two step sequence)
0 to 13	0 to 12	Switch directly to target RSEL

AND

- When switching RSEL from <12 to >13 it's recommended to set RSEL to its default value first (RSEL = 7) before switching to the desired target frequency.

AND

- In case RSEL is at 15 (highest setting) it's recommended to set RSEL to its default value first (RSEL = 7) before accessing DCOCTL to modify the DCOx and MODx bits. After the DCOCTL register modification the RSEL bits can be manipulated in an additional step.

In the majority of cases switching directly to intermediate RSEL steps as described above will prevent the occurrence of BCL12. However, a more reliable method can be implemented by changing the RSEL bits step by step in order to guarantee safe function without any dead time of the DCO.

Note that the 3-step clock startup sequence consisting of clearing DCOCTL, loading the BCSTL1 target value, and finally loading the DCOCTL target value as suggested in the in the "TLV Structure" chapter of the [MSP430x2xx Family User's Guide](#) is not affected by BCL12 if (and only if) it is executed after a device reset (PUC) prior to any other modifications being made to BCSTL1 since in this case RSEL still is at its default value of 7. However any further changes to the DCOx and MODx bits will require the consideration of the workaround outlined above.

BCL13***BCL Module*****Category**

Functional

Function

DCO powerup halt

Description

When subject to very slow Vcc rise times, the device may enter into a state where the DCO does not oscillate. No JTAG access or program execution is possible and the device will remain in a reset state until the supply voltage is disconnected.

Workaround

Apply a Vcc poweron ramp $\geq 10\text{V/second}$ under all power-on/power-cycle scenarios.

BCL14***BCL Module*****Category**

Functional

Function

Oscillator fault forced in bypass mode when P2SEL.7 bit is not set

Description

When the LFXT1 oscillator is used in bypass mode and P2SEL.7 is not set, the oscillator fault flag (OFIFG) will be forced to set and cannot be cleared. Due to the failsafe logic, LFXT1 cannot be used as MCLK in this case. The bug only affects the behavior of the oscillator fault, the clocking itself works properly.

Workaround

Set both P2SEL.6 and P2SEL.7 if the application requires correct function of the oscillator fault flag (e.g. MCLK failsafe logic).

Note

Setting P2SEL.7 bit disables the GPIO functionality and enables the input schmitt trigger of the pin. P2.7 should be tied to a fixed voltage level (VCC or GND) to prevent cross current.

BSL5***BSL Module*****Category**

Software in ROM

Function

BSL might not start if RST/NMI pin is configured as NMI input

Description

If the RST/NMI pin is configured to NMI, the bootstrap loader may not be started. Unpredictable operations will result.

Workaround

None

CPU4

CPU Module

Category

Compiler-Fixed

Function

PUSH #4, PUSH #8

Description

The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, -1) can be used. The number of clock cycles is different:

PUSH #CG uses address mode 00, requiring 3 cycles, 1 word instruction

PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2 word instruction

Workaround

Refer to the table below for compiler-specific fix implementation information.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	IAR EW430 v2.x until v6.20	User is required to add the compiler flag option below. --hw_workaround=CPU4
IAR Embedded Workbench	IAR EW430 v6.20 or later	Workaround is automatically enabled
TI MSP430 Compiler Tools (Code Composer Studio)	v1.1 or later	
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 4.9 build 167 or later	

CPU5

CPU Module

Category

Functional

Function

Interrupt handler, incorrect interrupt vector fetch

Description

When an interrupt is accepted and the interrupt vector is applied to the MAB, an interrupt vector

address 32 bytes lower than the expected address may be applied to the address bus.

This is true

only when the stack pointer address is in one of the following ranges:

0x02C0 to 0x02DF

0x0280 to 0x029F

0x0240 to 0x025F

0x0200 to 0x021F

Workaround

Solution #1: Limit stack depth to 32 bytes.

OR

Solution #2 (Recommended, works under all conditions): Copy the interrupt vector table (0xFFE0 to

0xFFFF) in flash to addresses 0xFFC0 to 0xFFDF, respectively.

CPU6

CPU Module

Category

Compiler-Fixed

Function

Incorrect execution of ADD instruction

Description

When the CPU executes an ADD (.B or .W) instruction using indirect addressing mode with destination R1 or R4 to R15, directly after a RET or RETI instruction, the addition will

be executed twice. This bug does not apply in the case that the indirect source working register is R2 or R3 (constant generator access for #2 or #4 are valid).

The instruction word mask that corresponds to the CPU6 condition is as follows:

Format I Instruction
(See *MSP430x2xx Family User's Guide*)

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0	
op-code				s-reg				Ad	B/W	As		d-reg				
MSB																LSB
0	1	0	1	X	X	X	X	0	X	1	0	X	X	X	X	

X = Don't care
s-reg = R2 or R3 are not affected
d-reg = R0, R2, or R3 are not affected

Workaround

1. (Preferred) Use indexed addressing with offset 0 instead of indirect addressing:
ADD(.B/.W) 0(R10),R11

Note that some assemblers may convert this instruction to indirect addressing.

Alternatively, when the source is in assembly, making the following changes works around the bug. Perform the following only if Workaround 1 cannot be implemented.

or

2. Place an instruction (for example NOP) between any instances of CALL and ADD(.B/.W) instructions where the ADD immediately follows the CALL.

or

3. Replace all RETI instructions with 'DW 01301h'. The instruction word for RETI is 01300h. By replacing this directly in assembly with 01301h, the bug is avoided and the RETI instruction is executed properly; for example:

```
WDT_ISR ; Exit LPM3 on reti
bic.w #LPM3,0(SP) ;
;reti ; Replace RETI with
DW 01301h ; this line of code
```

Refer to the table below for compiler-specific fix implementation information.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	IAR EW430 v4.x or later	User is required to add the compiler flag option below. --hw_workaround=CPU6 Add -h option for Assembler
TI MSP430 Compiler Tools (Code Composer Studio)	Fix not available	
MSP430 GNU Compiler (MSP430-GCC)	Fix not available	

CPU11

CPU Module

Category

Functional

Function	Invalid status register after program counter access
Description	When addressing the program counter (PC) in register mode where the PC is the destination, the Status Register (SR) may be erroneous. The instructions BIS, BIC and MOV do not affect SR contents. Only CPU flags are effected: DOES NOT apply to LPMx control bits.
Workaround	None

CPU12 *CPU Module*

Category Compiler-Fixed

Function CMP or BIT instruction with PC as destination

Description Instructions immediately following a CMP(.B) or BIT(.B) instruction that use the Program Counter (PC) as the destination register will be ignored or erroneously executed. When the following instruction is longer than one word, the second word is fetched by the CPU and decoded as the instruction, leading to unpredictable behavior. Affected source addressing modes are indexed and indirect addressing modes.

Example:
`cmp &200,PC`
`add #4,R8`

In this example, the add instruction will not be executed.

Workaround Insert a NOP instruction after the BIT or CMP instruction. The NOP will be ignored and program execution will continue as expected.

Refer to the table below for compiler-specific fix implementation information.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	Fix not available	
TI MSP430 Compiler Tools (Code Composer Studio)	15.12.0.LTS	User is required to add the compiler or assembler flag option below. --silicon_errata=CPU12
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 4.9 build 389 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu12
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 5.x build 14 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu12 -msilicon-errata-warn=cpu12 generates a warning in addition

CPU13 *CPU Module*

Category Compiler-Fixed

Function Arithmetic operations on the Status Register may lead to erroneous results

Description Performing arithmetic operations with the Status Register (SR) as the destination address will not update the SR as intended. The result in SR may be invalid, leading to erroneous

low power mode entry. Arithmetic operations are defined as all instructions that modify the SR flag bits (RRA, SUB, XOR and ADD for example).

Workaround

Refer to the table below for compiler-specific fix implementation information.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	Fix not available	
TI MSP430 Compiler Tools (Code Composer Studio)	15.12.0.LTS	User is required to add the compiler or assembler flag option below. --silicon_errata=CPU13
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 4.9 build 389 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu13 -msilicon-errata-warn=cpu13 generates a warning in addition
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 5.x build 14 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu13 -msilicon-errata-warn=cpu13 generates a warning in addition

CPU14**CPU Module****Category**

Functional

Function

Erroneous setting of SCG0 after reset

Description

The SCG0 bit in the CPU status register (SR) is set after any reset (PUC or POR) if bit #6 in the reset vector destination address is set. Setting SCG0 turns off the DCO dc generator when DCOCLK is not used for MCLK or SMCLK.

Workaround

1) As the error only occurs after PUC or POR, it is sufficient to clear the SCG0 bit at the beginning of the program code; for example:
bic.w #SCG0, SR

OR

2) Avoid using reset destination addresses where bit #6 is set. Allowed reset vector destination addresses are: xx0xh, xx1xh, xx2xh, xx3xh, xx8xh, xx9xh, xxAxh, xxBxh.

CPU19**CPU Module****Category**

Compiler-Fixed

Function

CPUOFF modification may result in unintentional register read

Description

If an instruction that modifies the CPUOFF bit in the Status Register is followed by an instruction with an indirect addressed operand (e.g. MOV @R8, R9, RET, POP, POPM), an unintentional register read operation can occur during the wakeup of the CPU. If the unintentional read occurs to a read sensitive register (e.g. UCB0RXBUF, TAIV), which changes its value or the value of other registers (IFG's), the bug leads to lost interrupts or wrong register read values.

Workaround

Insert a NOP instruction after each CPUOFF instruction.

OR

Refer to the table below for compiler-specific fix implementation information. Note that compilers implementing the fix may lead to double stack usage when RET/RETA follows the compiler-inserted NOP.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	IAR EW430 v6.20.1 until v6.40	User is required to add the compiler or assembler flag option below. --hw_workaround=nop_after_lpm
IAR Embedded Workbench	IAR EW430 v6.40 or later	Workaround is automatically enabled
TI MSP430 Compiler Tools (Code Composer Studio)	15.12.0.LTS	User is required to add the compiler or assembler flag option below. --silicon_errata=CPU19
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 4.9 build 389 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu19 -msilicon-errata-warn=cpu19 generates a warning in addition
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 5.x build 14 or later	User is required to add the compiler or assembler flag option below. -msilicon-errata=cpu19 -msilicon-errata-warn=cpu19 generates a warning in addition

CPU45

CPU Module

Category

Functional

Function

CPU speed performance limitation

Description

The CPU register contents may become unpredictable during CPU register operations if the device operates at minimum Vcc required for system speed performance above 6MHz when using LFXT1 in HF mode (BCSCTL1.XTS = 1) and sourcing MCLK to clock the CPU under certain conditions. This is dependent on voltage and CPU clock (MCLK) frequency and duty-cycle.

Workaround

With respect to the system speed performance above 6MHz versus minimum required Vcc

1. Use external clocks with 50% positive duty cycle when sourced to MCLK
OR
2. Use internally divided clock for MCLK (BCSCTL2.DIVMx > 00)
OR
3. Reduce LFXT1 (used in HF mode) or external clock frequency by 20% when sourced to MCLK

EEM20

EEM Module

Category

Debug

Function

Debugger might clear interrupt flags

Description	During debugging read-sensitive interrupt flags might be cleared as soon as the debugger stops. This is valid in both single-stepping and free run modes.
Workaround	None.
FLASH16	<i>FLASH Module</i>
<hr/>	
Category	Functional
Function	Modifying INFOA addresses when LOCKA = 1 will modify main flash memory
Description	When attempting to write to an address location or perform a segment erase of INFOA while the LOCKA bit is set, flash memory beginning at main memory location 0xFC40 and extending for 64 bytes to address 0xFC7F will be modified erroneously. These 64 bytes are addressed and modified in place of the INFOA addresses when writes or erases are performed within the INFOA address space and LOCKA = 1.
Workaround	Prior to modifying (writing or erasing) any address within the INFOA Flash memory segment, properly clear the LOCKA control bit as described in the MSP430x2xx User's Guide (SLAU144) to unlock the segment. Once the modification is complete, setting the LOCKA bit is recommended.
FLASH17	<i>FLASH Module</i>
<hr/>	
Category	Functional
Function	Flash read when EEI = 1
Description	When a segment erase in FLASH is initialized and the erase cycle is interrupted, any read from FLASH may be erroneous until after the erase cycle is completed.
Workaround	When EEI = 1, initiate all FLASH segment erases using a byte access to an even address within the segment to be erased. For example: (Assembly) mov.b #0FFh, &1000h (C) *(char*)0x1000 = 0; //ERASE
FLASH18	<i>FLASH Module</i>
<hr/>	
Category	Functional
Function	Information flash access when EEI = 1
Description	When a segment erase to any flash location has been initiated and the erase cycle has been interrupted, it is not possible to read from the information flash memory locations until the erase cycle is completed.
Workaround	None
FLASH19	<i>FLASH Module</i>
<hr/>	
Category	Functional
Function	EEI feature does not work for code execution from RAM
Description	When the program is executed from RAM, the flash controller EEI feature does not work. The erase cycle is suspended and the interrupt is serviced, but there is a problem while

resuming with the erase cycle.

Addresses applied to flash are different than the actual values while resuming erase cycle after ISR execution.

Workaround None

FLASH20 *FLASH Module*

Category Functional

Function Flash erase is not correctly executed when EEI is enabled and interrupts occur

Description Flash erase is not executed correctly when EEI is enabled and an interrupt occurs in a certain time window. The BUSY signal from the flash controller and the "JMP \$" feature, that keeps the program counter at the current position, disappear shortly after a flash erase cycle has been initialized.

Workaround None

FLASH22 *FLASH Module*

Category Functional

Function Flash controller may prevent correct LPM entry

Description When ACLK (or SMCLK) is used as the flash controller clock source, and this clock source gets deactivated due to a low-power mode entry while a flash erase or write operating is pending, the flash controller will keep ACLK (or SMCLK) active even after the flash operation has been completed. This will result in an incorrect LPM entry and increased current consumption. Note that this issue can only occur when the Flash operation and the low-power mode entry are initiated from code located in RAM.

Workaround Do not enter low-power modes while flash erase or write operations are active. Wait for the operation to be completed before entering a low-power mode.

FLASH24 *FLASH Module*

Category Functional

Function Write or erase emergency exit can cause failures

Description When a flash write or erase is abruptly terminated, the following flash accesses by the CPU may be unreliable resulting in erroneous code execution. The abrupt termination can be the result of one the following events:

1) The flash controller clock is configured to be sourced by an external crystal. An oscillator fault occurs thus stopping this clock abruptly.

or

2) The Emergency Exit bit (EMEX in FCTL3) when set forces a write or an erase operation to be terminated before normal completion.

or

3) The Enable Emergency Interrupt Exit bit (EEIEX in FCTL1) when set with GIE=1 can lead to an interrupt causing an emergency exit during a Flash operation.

Workaround 1) Use the internal DCO as the flash controller clock provided from MCLK or SMCLK.

or

2) After setting EMEX = 1, wait for a sufficient amount of time before Flash is accessed again.

or
3) No Workaround. Do not use EEIEX bit.

FLASH27**FLASH Module**

Category

Functional

Function

EEI feature can disrupt segment erase

Description

When a flash segment erase operation is active with EEI feature selected (EEI=1 in FLCTL1) and GIE=0, the following can occur:

An interrupt event causes the flash erase to be stopped, and the flash controller expects an RETI to resume the erase. Because GIE=0, interrupts are not serviced and RETI will never happen.

Workaround

1) Do not set bit EEI=1 when GIE = 0.
or,
2) Force an RETI instruction during the erase operation during the check for BUSY=1 (FCTL3).

Sample code:

```
MOV R5, 0(R5) ; Dummy write, erase segment
LOOP: BIT #BUSY, &FCTL3 ; test busy bit
JMP SUB_RETI ; Force RETI instruction
JNZ LOOP ; loop while BUSY=1
```

```
SUB_RETI: PUSH SR
RETI
```

FLASH36**FLASH Module**

Category

Functional

Function

Flash content may degrade due to aborted page erases

Description

If a page erase is aborted by EEIEX, the flash page containing the last instruction before erase operation will start to degrade. This effect is incremental and, after repetitions, may lead to corrupted flash content.

Workaround

- Use the EEI (interrupted erasing) feature instead of EEIEX (abort erasing).
or
- A PSA checksum can be calculated over affected flash page using the marginal read mode (marginal 0). If PSA sum differs from expected PSA value the affected flash page has to be reprogrammed.
or
- Start flash erasing from RAM and limit system frequency to <1MHz (to ensure 6-us delay after EEIEX). If the last instruction before erasing is located in RAM, flash cell degradation does not occur.

JTAG15**JTAG Module**

Category

Debug

Function

Using TDO as input for TDI does not work when JTAG is used to drive the MAB

Description When the TDO is used as TDI, the MAB is not correctly driven by JTAG. This causes problems when using the function GangProgramTarget() of the GANG430.DLL. This function is usually used for programming individual serial numbers, for programming calibration data into devices, and for restoration of DCO calibration data after erasing of segment A.

Workaround Upgrade to GANG430.DLL version 1.42 or higher.

PORT8 *PORT Module*

Category Functional

Function Increased leakage current

Description The LFXT1 oscillator circuit is not disabled when P2SEL.6 = 0 or P2SEL.7=0. This can result in a higher leakage current on P2.7 XOUT when P2DIR.7 = 0 and P2SEL.7=0.

Workaround If using P2.7 as an input, select the bypass mode by setting the LFXT1Sx = 11

PORT10 *PORT Module*

Category Functional

Function Pull-up/down resistor selection when module pin function is selected

Description When the pull-up/down resistor for a certain port pin is enabled (PxREN.y=1) and the module port pin function is selected (PxSEL.y=1), the pull-up/down resistor configuration of this pin is controlled by the respective module output signal (Module X OUT) instead of the port output register (PxOUT.y).

Workaround None. Do not set PxSEL.y and PxREN.y at the same time.

SYS15 *SYS Module*

Category Functional

Function LPM3 and LPM4 currents exceed specified limits

Description LPM3 and LPM4 currents may exceed specified limits if the SMCLK source is switched from DCO to VLO or LFXT1 just before the instruction to enter LPM3 or LPM4 mode.

Workaround After clock switching, a delay of at least four new clock cycles (VLO or LFXT1) must be implemented to complete the clock synchronization before going into LPM3 or LPM4.

TA12 *TA Module*

Category Functional

Function Interrupt is lost (slow ACLK)

Description Timer_A counter is running with slow clock (external TACLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by one with the occurring compare interrupt (if TAR = CCRx). Due to the fast MCLK the CCRx register increment (CCRx = CCRx+1) happens before the Timer_A counter has incremented again. Therefore the next compare interrupt should happen at once with the next Timer_A counter increment (if TAR = CCRx + 1). This interrupt gets lost.

Workaround Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterwards.

TA16

TA Module

Category Functional

Function First increment of TAR erroneous when IDx > 00

Description The first increment of TAR after any timer clear event (POR/TACLr) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.

Workaround None


TA21

TA Module

Category Functional

Function TAIFG Flag is erroneously set after Timer A restarts in Up Mode

Description In Up Mode, the TAIFG flag should only be set when the timer counts from TACCR0 to zero. However, if the Timer A is stopped at TAR = TACCR0, then cleared (TAR=0) by setting the TACLr bit, and finally restarted in Up Mode, the next rising edge of the TACLK will erroneously set the TAIFG flag.



Workaround None.

TAB22

TAB Module

Category Functional

Function Timer_A/Timer_B register modification after Watchdog Timer PUC

Description Unwanted modification of the Timer_A/Timer_B registers TACTL/TBCTL and TAIV/TBIV can occur when a PUC is generated by the Watchdog Timer(WDT) in Watchdog mode and any Timer_A/Timer_B counter register TACCRx/TBCCRx is incremented/decremented (Timer_A/Timer_B does not need to be running).

Workaround Initialize TACTL/TBCTL register after the reset occurs using a MOV instruction (BIS/BIC may not fully initialize the register). TAIV/TBIV is automatically cleared following this initialization.

Example code:

```
MOV.W #VAL, &TACTL
or
```

MOV.W #VAL, &TBCTL

Where, VAL=0, if Timer is not used in application otherwise, user defined per desired function.

XOSC5

XOSC Module

Category

Functional

Function

LF crystal failures may not be properly detected by the oscillator fault circuitry

Description

The oscillator fault error detection of the LFXT1 oscillator in low frequency mode (XTS = 0) may not work reliably causing a failing crystal to go undetected by the CPU, i.e. OFIFG will not be set.

Workaround

None

XOSC8

XOSC Module

Category

Functional

Function

ACLK failure when crystal ESR is below 40 kOhm.

Description

When ACLK is sourced by a low frequency crystal with an ESR below 40 kOhm, the duty cycle of ACLK may fall below the specification; the OFIFG may become set or in some instances, ACLK may stop completely.

Workaround

Please refer to "XOSC8 Guidance" found at [SLAA423](#) for information regarding working with this erratum.

7 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from May 29, 2018 to May 11, 2021	Page
<ul style="list-style-type: none">Changed the document format and structure; updated the numbering format for tables, figures, and cross references throughout the document.....	6

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2022, Texas Instruments Incorporated