

3458A-08A

S E R V I C E N O T E

Supersedes:
3458A-08


3458A Multimeter

Serial Numbers: 0000A00000 / 2823A06785

Incorrectly Labeled Line Voltage Switches May Cause Switch Setting Confusion

Situation:

Some units may have incorrectly labeled line voltage selection switches installed. The correct settings are silkscreened on the instrument rear panel. The incorrect settings are silkscreened on the voltage selection switches themselves.



Solution/Action:

No action is required. However, to avoid confusion, the incorrectly silkscreened line voltage may be easily scratched off using a small flat-head screwdriver.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: DLL PRODUCT LINE: 09E
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



April 10, 2002