E4980A Precision LCR Meter, Firmware Revision History

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Agilent representative.

Revision 3.00 … Released Jun. 2013

1. Added new options (Opt.030/050/100/200)
2. Fixed bug on entering "-" manually

Revision 2.21 … Released Aug. 2011
1. Fixed bug on LAN Socket.

Revision 2.21 … Released Aug. 2011
1. Fixed bug on LAN Socket.

Revision 2.20 … Released Jul. 2009
1. Fixed bug on I/O error through device side USB control.

Note: For MY46204137 and above, the firmware revision 2.20 and later can only be installed. Do NOT attempt to install the older firmware revisions.

Revision 2.13 … Released Nov. 2007
1. Fixed bug on signal output during Step Delay time in L-Rdc measurement mode (Opt 001).

Revision 2.12 … Released Aug. 2007
1. Corrected DC Bias current setting resolution on Option 002 (40 A configuration).
2. Fixed bug on INDEX/EOM output at Open/Short/Load correction.
3. Fixed bug with INDEX/EOM output on Scanner Interface (Opt. 301).

Revision 2.10 … Released Apr. 2007
1. Added function for selecting DC Bias Range (Auto On/Off).
2. Fixed open correction issue.

Revision 2.00 … Released Nov. 2006
1. Added functions for LXI class C.
2. Fixed DNS server issue.
3. Fixed DHCP server issue.

Revision 1.05 … Released Aug. 2006
1. Fixed OPE/SHORT correction issue.

Revision 1.04 … Released Jul. 2006
1. Fixed LIST:STM:TYPE command issue.
2. Fixed recall function issue.

Revision 1.03   … Released Jun. 2006
   1. Added avoidance routine for "boot fail".

Revision 1.02   … Released Jun. 2006
   1.   Changed DC bias list sweep sequence.
   2.   Changed OPC? Command specification.

Revision 1.01   … Released Apr. 2006
   1.   Changed Handle I/F output specification when "Fixture cover open" message is displayed.

Revision 1.00   … Released Mar. 2006
   1.   Initial Release.