



HMC-VVD106 Temperature = +25C

Insertion Loss




HMC-VVD106 Temperature = +25C

Input Return Loss




HMC-VVD106 Temperature = +25C

Output Return Loss




HMC-VVD106 Temperature = +25C

Relative Insertion Loss




HMC-VVD106 Temperature = +25C


Relative Insertion Phase




HMC-VVD106 Temperature = +25C
Insertion Loss



HMC-VVD106 Temperature = +25C
Relative Insertion Loss



HMC-VVD106 Temperature = +25C
Relative Insertion Phase



HMC-VVD106 Temperature = +25C
Current

