

Home



Why do I get a message telling me that I need Option B72 when I try to load the latest version of firmware into my ESA Spectrum Analyzer?

Firmware versions A.08.02 or later require a larger amount of memory to load into the [ESA Spectrum Analyzer](#). This increase in the size is due to the added features it contains. If you get this message when you try to update your firmware you have two choices on what you can do:

- Order Option B72 so that you can take advantage of the new feature set. You can do this by ordering it as E440xBU-B72¹.
- Upgrade to the latest version of firmware that will fit into an analyzer without Option B72. This would be version A.07.06. This version can be downloaded from the web at [ESA Spectrum Analyzer Firmware, A.07.06](#)

¹Place the order based on your ESA model number. For example, **E4407BU-B72**.

Was this helpful? ☒ Yes ☐ No

Didn't find what you're looking for?

[Contact Support](#)

DISCOVER

- Products + Services
- Solutions
- Industries
- Events
- Keysight University

SUPPORT

- Keysight Product Support
- Ixia Product Support
- Manage Software Licenses

EXPLORE

- Success Stories
- Resources
- Blog
- Community

PARTNERS

ABOUT KEYSIGHT

- Newsroom
- Investor Relations
- Corporate Social Responsibility





Product Order Status

Diversity, Equity, and Inclusion

Parts

Modern Slavery Act Transparency Statement

Careers

-  Facebook: Connect with Keysight
-  LinkedIn: Connect with Keysight
-  Twitter: Connect with Keysight
-  YouTube: Connect with Keysight