


This jumper restores the connection cut for the 110 V version



To Convert 110 V to a 220 V board:
1. Make three cuts shown above in red.
2. Attach two jumpers shown above in green.

CIRCUIT SIDE GC 94V-0