



SUMMARY OF CHANGES

IFR 6000 XPDR/DME/TCAS/ADS-B/TIS/TIS-B TEST SET SOFTWARE/FIRMWARE UPGRADE

Purpose

The purpose of this document is to describe the changes from Software Version 1.05.00 to 1.08.00 for the IFR 6000.

Contact Aeroflex for more information:

Aeroflex
Customer Service Dept.
10200 W. York
Wichita, KS 67215

Telephone: (800) 835-2350
FAX: (316) 524-2623
Email: americas.service@aeroflex.com

Corrections/Enhancements

DME Mode:

- None

XPDR Mode:

- In ADS-B mode, fixed BDS 1,8 – 1,C data fields that were being listed in reverse order

TCAS Mode:

- Fixed incorrect Mode C altitude pulses in TCAS Diagnostics that occurred when a certain key sequence was done.

General:

- Corrected a problem to allow the USB upgrades to handle certain files better.
- Corrected a problem to make the corrupting of saved calibrations less likely to occur.