

# Appendix C: Default Factory Settings

Table C 1 lists the instrument settings after Default Factory Settings have been recalled.

CTS 850 SDH/PDH Test Set

**Table C 1: Default Factory Settings**

Parameter	Default Value
Transmit Rate	STM-1E
Transmit Clock	Internal
Transmit Level	6 dB
AU Under Test	1
Mapping	Bulk Fill No Mapping (Equipped)
Transmit Test Pattern	PRBS 2 <sup>23</sup> - 1
Transmit Overhead Path Trace	This is a Tektronix CTS Test Set
Transmit Overhead External Add	None
Transmit Error Rate	None
Transmit Error Type	None
Transmit Alarm	None
Transmit Failure	None
Transmit Pointer/Timing Mode	Pointer Movements
Transmit Pointer Type	AU
Transmit Pointer Control	Single
Transmit Pointer Value	522
Transmit Pointer Set with New Data Flag	Yes
APS Mode	SPAN
Receive Rate	STM-1E

**Table C 1: Default Factory Settings (Cont.)**

<b>Parameter</b>	<b>Default Value</b>
Receive Level	Cross Connect
Receive AU Under Test	1
Receive Mapping	No Mapping (Equipped)
Receive Tributary Drop	Off
Receive Test Pattern	PRBS 2 <sup>23</sup> 1
Test Duration	Continuous
Receive Path Overhead External Drop	None
Beeper	Off
Display Brightness	Medium, high
Printer Type	TEK DPU-411
Print User & Company	Off