



XP9

Адрес	Цепь	←
Жгут УШЯИ.685621.383	-15V	1
	-15V	3
	-15V	2
	32	6
	-50V	4
	-50V	5




XP10

Адрес	Цепь	←
Жгут УШЯИ.685621.383	-7.5V	1
	-7.5V	2
	-7.5V	2




XP11

Адрес	Цепь	←
Жгут УШЯИ.685621.384	-7.5V	1
	-7.5V	2
	-7.5V	3
	-7.5V	4



XS1.3

Цепь	↔
GND A	6
+8VA	7
-8VA	8
+5VA	9
GND A	10
GND D	11
+4VD	12
+2.5VD	13
+3.3VD	14
GND D	26
SIGNBITOUT	27
GND D	28



XS2

Цепь	Адрес
SCLK (L1,L2)	5
CE5 (L2)	4
GND D	3
SIGNBITOUT	2
GND D	1

XS3

Цепь	Адрес
IOUTB (L1)	1
IOUT (L1)	2
CE1 (L2)	3
SDI (L1,L2)	4
RESET (L2)	5
+4VD	6
GND D	7
GND	8
+5VA	9

