

Home



Why do I get an error whenever I try to create an installation disk set from a downloaded file for my ESA or EMC analyzer?

There could be a few different reasons for getting the following error when you try to create an installation disk set from a downloaded file for either ESA or EMC firmware, measurement personalities, or limit lines / transducer factors.



The possible causes and solutions for this error could be:

Possible Causes for Error	
Cause	Solution
Floppy drive was "Hot Swapped"	Re-boot computer with drive connected
Floppy Drive is connected via USB	Use a different computer with a non-USB drive
No floppy drive	Install a floppy drive or use a different computer that has one
Floppy drive or controller has a hardware failure	Fix the hardware problem or use a different computer

Was this helpful? Yes No

Didn't find what you're looking for?

[Contact Support](#)

DISCOVER

Products + Services

Solutions

Industries

Events

Keysight University

SUPPORT

Keysight Product Support

Ixia Product Support

Manage Software Licenses

Product Order Status

Parts

EXPLORE

Success Stories

Resources

Blog

Community

PARTNERS

ABOUT KEYSIGHT

Newsroom

Investor Relations

Corporate Social Responsibility

Diversity, Equity, and Inclusion

Modern Slavery Act Transparency Statement

Careers

 Facebook: Connect with Keysight

 LinkedIn: Connect with Keysight

 Twitter: Connect with Keysight

 YouTube: Connect with Keysight