

🏠 Marconi-Test-Instruments@groups.io (/g/Marconi-Test-Instruments)

Single ▾

🔊 Mute This Topic (/g/Marconi-Test-Instruments/ft/78246844/7784?csrf=5513314409256117711&mute=1&p=,,,20,0,0,0::Created,,lopt,20,2,0,78246844)

🔍 Search

Re: Marconi 2955, adapter PCB



george edmonds

Nov 14 🔗 (<https://groups.io/g/Marconi-Test-Instruments/message/7784>)

Hi Shane

Don't want to rain on your parade, but there are two versions of the E100521 LOPT. One version has the EHT cable entering at the side and the other version has it on the top. Only the side entry version will work correctly in a 2955 due to the metal sheild around the LOPT.

Now the photograph on the link you kindly provided shows a top entry version for the EHT cable, this may of course just be a stock photograph and not a photograph of the real item.

I have attached two photographs of the correct type.

I was aware of the two versions of the BU806, however, thank you for pointing it out it is very important to get the correct spec BU806. Two transistors with the same type number but different specifications is madness.

George G6HIG Dover UK

Show quoted text



(<https://groups.io/g/Marconi-Test-Instruments/attachment/7784/0/LOPT1.jpg>)



(<https://groups.io/g/Marconi-Test-Instruments/attachment/7784/1/LOPT2.jpg>)

↩ Reply

👍 Like

☰ More

[◀ \(/g/Marconi-Test-Instruments/message/7783\)](/g/Marconi-Test-Instruments/message/7783)

[View All 21 Messages In Topic \(/g/Marconi-Test-Instruments/topic/78246844#7784\)](/g/Marconi-Test-Instruments/topic/78246844#7784)

[▶ \(/g/Marconi-Test-Instruments/message/7785\)](/g/Marconi-Test-Instruments/message/7785)

[◀ \(/g/Marconi-Test-Instruments/message/7783\)](/g/Marconi-Test-Instruments/message/7783)

[#7784](#)

[▶ \(/g/Marconi-Test-Instruments/message/7785\)](/g/Marconi-Test-Instruments/message/7785)