





Part #:	<b>Digi AnyWhereUSB® Plus</b>	  
Description:	<ul style="list-style-type: none"> <li>• Network-attached USB hubs for USB 3.1 connectivity</li> <li>• Ideal for virtualized environments such as VMware®</li> </ul>	 <a href="#">Download Datasheet</a>

## EEVblog Electronics Community Forum

A Free & Open Forum For Electronics Enthusiasts & Professionals


### Hello volvo\_nut\_v70


Show unread posts since last visit.  
 Show new replies to your posts.  
 July 23, 2019, 06:13:04 am


 This topic 

-  Home
-  Help
-  Search
-  Profile
-  About us
-  My Messages
-  Calendar
-  Links
-  HashTags
-  Members
-  Logout

EEVblog Electronics Community Forum » Electronics » Repair » rohde schwarz SML 02 repair help please.

 **PCB Prototype for \$2**  
 ( Any Color )





**MSOX3104T \$6,633.09** ~~-\$7,370.10~~  
**Save an extra 10%!**

« previous next »

Pages: [1] **Go Down**

- [REPLY](#)
- [NOTIFY](#)
- [MARK UNREAD](#)
- [SEND THIS TOPIC](#)
- [PRINT](#)
- [SEARCH](#)

 Author


Topic: rohde schwarz SML 02 repair help please. (Read 635 times)

volvo\_nut\_v70 and 0 Guests are viewing this topic.

**eurgenca**

Contributor

Posts: 6

Country: 



 **rohde schwarz SML 02 repair help please.**

« on: December 03, 2018, 09:48:46 am »

[Say Thanks](#)

[Reply](#)

[Quote](#)

Hello.

I was looking for repair tip for sig. generator sml02 and found this site. So first I want to say Hello to all of you.

So I bought this sml on ebay with broken LCD. After replacing with new I can see that I have more problems 😞

After powering up I get error msg.

Module (0/CPU)

Missing data block

10401 / freq data ext

Then sml finish booting up and under error page I have 1 stored error.

315 configuration memory lost; EEPROM data

I check service manual and all info that I can get is that one or more data block is missing. But no info how to repair this. I try with calibration and all tests pass, but error remain. Can someone help me with this error.

Thanks and regards, Sebastijan.


[Report to moderator](#)

 Logged

**eurgenca**

Contributor

Posts: 6

Country: 

 **Re: rohde schwarz SML 02 repair help please.**

« Reply #1 on: December 04, 2018, 06:02:25 pm »

[Say Thanks](#)

[Reply](#)

[Quote](#)



Hello, again.

I found in manual that exist software SML SERVICE UTILITY, but I can't find it on the net. If someone here have this SW or link where to download, will be very happy.

Thanks, Sebastijan.

Report to moderator Logged

**analogRF**

Regular Contributor



Posts: 187

Country:



**Re: rohde schwarz SML 02 repair help please.**

Say Thanks Reply Quote

« Reply #2 on: April 20, 2019, 12:10:24 am »

**Quote from: eurgenca on December 04, 2018, 06:02:25 pm**

Hello, again.

I found in manual that exist software SML SERVICE UTILITY, but I can't find it on the net. If someone here have this SW or link where to download, will be very happy.

Thanks, Sebastijan.

were you able to find that software or to solve the problem with the instrument?

Report to moderator Logged

**eurgenca**

Contributor

Posts: 6

Country:



**Re: rohde schwarz SML 02 repair help please.**

Say Thanks Reply Quote

« Reply #3 on: April 20, 2019, 06:31:44 pm »

Hello.

This SW is for service center only, so probably nobody make a copy and release it on net.

I figure out that configuration error is due to wrong firmware update, but benefit is that frequency go to 3.3Ghz. So it is basically SML 03.

Regards, Seba.

Report to moderator Logged

Pages: [1] [Go Up](#)

[REPLY](#) [NOTIFY](#) [MARK UNREAD](#) [SEND THIS TOPIC](#) [PRINT](#) [SEARCH](#)  
« previous next »

Share me



EEVblog Electronics Community Forum » Electronics » Repair » rohde schwarz SML 02 repair help please.

[LINK TO CALENDAR](#)

Jump to: => Repair ▼ go

Quick Reply

**BUDGET MULTIMETERS !!**  
ANENG, UNI-T and more...

[EEVblog Main Site](#)

[EEVblog on Youtube](#)

[EEVblog on Twitter](#)

[EEVblog on Facebook](#)